## HAZARDOUS WASTE FACILITY INSPECTION FORM



Facility Name: Scientific Cher Processing	mical I.D. # 020574	Date: Time: 10:15
Facility Type: Transfer, Store	age, Processing	•
Street: Paterson Plank Road	d Lot:	Block:
Town: Carlstadt	Phone: 201-939-	-1116
County: Bergen	Person Contacted Position: Plant	•
Inspector: George Smajda		
Weather Conditions: Clear $\sqrt{xx}$	Rain // Snow //	
Wind Direction: W Temp	: 45 Speed <u>5-10 ME</u>	<u>ज</u> ्म
Security Measures: Fence $\sqrt{xx}$	Yes // No	
Guard //	Yes $\sqrt{xx}$ No	
Other Ope	rates 24 hours, 7 days	
Safety Features:  Firefighting XX/ Yes /  Type:	/ No	
Extinguisher XX/ Guns Protective Clothing: XX (Issued to Employees)	// Other // Extingui / Yes // No	isher needs recharging.
Written Emergency Procedu	ires Posted 📈 Yes 🖊	No ·
Inspection Observations:		
Odors: On Site 🚾 Yes 🖊	$\sqrt{}$ No Off Site $\sqrt{XX}$ Yes	s // No
Source: Still and thin fi	lm operations, off-site unkr	nown.
Leaks, Spills: On Site /XX	Yes / No Off Site	Yes / No
Source: Thin film area - d	rum storage, Tank T-10	,,,
Overall Housekeeping: Poor	<u> </u>	Excellent $\overline{//}$
Drum Storage:		
Total No. <u>2200+</u> Size	55 gal. Type r	netal
Stacked Height: 😿 1 Drum	// 2 Drums // 3 Drums	// 4 or more
Palletized: <u>kx/</u> Yes /x/x No	1600+ on pallets remaining drums on ground approximately 250 drums or	

Categorized: XX Yes // No Labeled: // Yes /XX No	
Manifested: // Yes /xk No See comments - No. 5	
Condition:	
Leaking: XX Yes // No Number of Leakers Unknown	
General Condition: /XX/ Poor // Fair // Good // Exce	llent
Vehicles: Registered $\boxed{\ \ }$ Yes $\boxed{\ \ }$ No No vehicles arriving	
Numbers Displayed // Yes // No	
Manifest Check: None on site	
Properly completed // Yes // No	•
Explain:	
Monitoring System: Air / Yes xx/ No	
Water // Yes kw/ No	
Does T.O.A. reflect capability: (Treatment/Processes) // Yes /	/ No N/A
Explain:	
Samples Gathered: // yes /xx no Number	
Photos: // Yes xx/ No No. Location:	
1	
2	
3	
4	
5	
Thursday of the Color of Comments	
Discryptions and/or Other Comments  1. All storage tanks have same material contained as last inspect	ion No change in this
material. All contain paint pigment, water, and solvent. Tan	·
from thin film.	
2. Thin film area has red liquid contained in dike area. Observe	d possible surface run-orr
from this area to creek.	
3. Distillation unit has purple stained crushed rock in area. The a new spill.	
ector's Signature.	•

## SCP - CARLSTADT Observations and/or Other Comments

	Observations and/or Other Comments
 4.	Seepage into creek near fuel tanks observed.
 5.	Observed 27 drums on trailer near pad with manifest #'s C25049 and 25034.
 6	Drum pad has multi-colored materials on top and sides.
7.	Tank T-10, containing thin film still bottoms has several holes and leaks. Material
	leaking onto ground.
8.	Approximately 1800 drums on ground area for storage. About 2 open tops covered
	with plastic lid. Approximately 1600 drums neatly stacked. Leakage, spillage, damaged,
 	and rusted drums observed. Observed red, brown, and milky white substances on ground.
	Mr. Barnes states that all drums are paint pigments and that all liquids have been
	pumped off for fuel blending.
 *	·
 <u> </u>	
 	•
 ······································	

Inspector's Signature

George Amuela\_

Facility Operator's Signature